## 7'S 6x9 DATA SHEETS. e paid for a scepted. Only data not available in engineers' handbooks desired.

PUNCH

PUNCH

PUNCH

CREASE HERE

These data sheets are intended to be cut into four sections,  $6 \times 9$  inches in size. The may then be bound into note-book form for convenient reference, by means of staple inserted in holes punched at the points indicated. A suitable binder for these dat sheets will be supplied for 25 cents, which has an open back and will hold an indefinit number of  $6 \times 9$  sheets, depending on the length of staples used.

1	DIMENS	IONS OF	CAST-	RON FLA	NGED FI	TTINGS,	TO WIT	HSTAND	100 POU	NDS TO	THE SQU	JARE INC	H.
A	В ,	c	D	E	F	G	н	1	J	к	L	M	N
2	.39	.69	.25	4.5	4.5	3.0	9.0	11.0	6.00	4- 1/2	4%	3.25	8.0
2½	.39	.69	.25	5.0	5.0	3.0	10.0	12.0	7.00	4- 1/2	5½	3.75	9.2
3	.41	.72	.25	5.5	5.5	3.0	10.5	13.0	7.50	4- 1/2	6	4.00	9.7
3½	.43	.76	.25	6.0	6.0	3.5	12.0	14.5	8.50	4- 1/2	7	4.50	11.0
4	.45	.79	.25	6.5	6.5	3.5	12.5	15.0	9.00	4- 5/8	7½	4.75	11.
4½	.46	.81	.25	6.5	6.5	4.0	13.5	16.5	9.25	8- %	7¾	5.25	12.
5	.48	.84	.25	7.0	7.0	4.0	14.0	17.0	10.00	8- %	8½	5.25	13.
6	.51	.90	.25	7.5	7.5	4.5	15.5	19.0	11.00	8- 5/8	9½	5.75	14.
7	.55	.97	.32	8.5	8.5	5.0	17.5	21.0	12.50	8- %	10%	6.50	16.
8	758	1.02	.32	9.0	9.0	5.0	18.5	22.5	13.50	8- %	11%	7.25	17.
9	.61	1.07	.32	10.0	10.0	5.5	20.5	24.5	15.00	12- %	1314	8.00	19.
10	.65	1.14	.32	10.5	10.5	6.0	22.0	26.5	16.00	12- ¾	1414	8.50	20.
12	.71	1.19	.32	12.0	12.0	6.5	25.5	30.5	19.00	12- 1/8	17	10.00	24.
14	.78	1.37	.38	13.5	13.5	7.5	28.5	34.5	21.00	12- 1/8	18¾	11.00	27.
15	.81	1.42	.38	14.0	14.0	7.5	30.0	36.0	22.25	16- 1/8	20	11.75	28.
16	.85	1.49	.38	15.0	15.0	8.0	31.5	38.0	23.50	16- 1/8	211/4	12.50	30.
18	.91	1.60	.38	16.0	16.0	8.5	33.5	40.5	25.00	16-1	22¾	13.25	32.
20	.98	1.73	.50	17.0	17.0	9.0	36.5	44.5	27.50	20-1	25	14.50	36.
22	1.05	1.84	.50	18.5	18.5	10.0	39.5	48.0	29.50	20-1	271/4	15.50	38.
24	1.11	1.95	.50	20.0	20.0	10.5	42.0	53.0	31.50	20-1	29½	16.50	40.

Contributed.

Supplement to MACHINERY, April, 1905.

A	В	C	D	E	F	G	н	1	1	K -	L	М	N
2	.46	.81	.25	5.0	5.0	3.0	9.5	12.0	6.50	4- 5%	5	3.50	8.7
2½	.48	.84	.25	5.5	5.5	3.5	11.0	13.5	7.50	4- 3/4	5%	4.00	10.0
3	51،	.90	.25	6.0	6.0	3.5	12.0	14.5	8.25	8- 5/8	65%	4.50	11.0
3½	.55	.97	.32	6.5	6.5	4.0	13.0	15.5	9.00	8- 5/8	71/4	4.75	12.0
4	.58	1.03	.32	7.5	7.5	4.5	14.5	17.5	10.00	8- 3/4	7%	5.50	13.2
4½	.61	1.07	.32	7.5	7.5	4.5	15.0	18.5	10.50	8- 34	8½	5.75	13.7
5	.65	1.14	.32	8.0	8.0	5.0	16.0	19.5	11.00	8- 34	91/4	6.00	14.5
6	.71	1.25	.32	9.0	9.0	5.0	17.5	21.5	12.50	12- ¾	10%	6.75	16.5
7	.78	1.37	.38	10.0	10.0	6.0	20.0	24.5	14.00	12- 1/8	11%	7.50	18.5
8	.85	1.49	.38	10.5	10.5	6.5	21.5	26.5	15.00	12- %	13	8.25	19.7
9	.91	1.59	.38	11.5	11.5	6.5	22.5	28.0	16.00	12- 1/8	14	8.75	21.2
0	.98	1.75	.50	12.5	12.5	7.5	25.0	31.0	17.50	16- %	151/4	9.50	23.2
2	1.11	1.95	.50 *	14.0	14.0	8.5	28.5	35.0	20.00	16- 1/8	17%	10.75	26.5
4	1.25	2.19	.63	16.0	16.0	9.5	32.0	39.5	22.50	20- ¾	20	12.25	29.7
5	1.31	2.30	.63	16.5	16.5	10.0	33.5	41.5	23.50	20-1	21	12.75	31.0
6	1.38	2.42	.63	17.5	17.5	10.5	35.0	44.0	25.00	20-1	221/4	13.50	33.0
8	1.51	2.64	.75	19.0	19.0	11.0	38.0	47.0	27.00	24-1	24½	14.75	35.7
0	1.65	2.90	.75	21.0	21.0	12.0	41.5	51.5	29.50	24-11/8	26¾	16.00	39.0
2	1.78	3.06	.75	22.0	22.0	13.0	44.5	55.5	31.50	28-11/8	28¾	17.25	41.5
4	·1.91	3.34	.75	24.0	24.0	14.0	48.0	60.0	34.00	28-11/8	311/4	18.50	45.0

Contributed.

Supplement to MACHINERY, April, 1905.